



Western Michigan University  
ScholarWorks at WMU

---

Legacy Scout Tickets from Pure Oil Company

---

8-20-2021

**MGRRE\_PureOilScoutTickets\_Griffin\_1\_21129016710000**

MGRRE

*Western Michigan University*

Follow this and additional works at: <https://scholarworks.wmich.edu/pure>



Part of the Geology Commons

---

#### WMU ScholarWorks Citation

MGRRE, "MGRRE\_PureOilScoutTickets\_Griffin\_1\_21129016710000" (2021). *Legacy Scout Tickets from Pure Oil Company*. 7743.

<https://scholarworks.wmich.edu/pure/7743>

This Document is brought to you for free and open access via ScholarWorks at WMU. It has been accepted for inclusion in Legacy Scout Tickets from Pure Oil Company by an authorized administrator of ScholarWorks at WMU. See the National Digital Catalogue - Science Base Catalogue for more collections submitted by MGRRE.



---

**MGRRE\_PureOilScoutTickets\_Griffin\_1\_21129016710000**

API 21129016710000

Permit Number 1671

Lease Name Griffin

Well Number 1

County Ogemaw

Township 22N

Range 02E

Section 29

2021 DEQ or Pure co\_name Sovereign, W. J.

Pure Number 42

Latitude 44.2683

Longitude -84.22432

THE PURE OIL COMPANY

DATE October 6, 1933Change of

LOCATION REPORT

No. 42STATE Michigan COUNTY Ogemaw DIST. West Branch SEC. 29 TOWN 22 N RANGE 2EWELL No. 1 (SERIAL No. 42) FARM Mary Griffin ACRESNAME OF STREAM OR WATERS QUADRANGLE NW-NW-SWOPERATOR W. J. Sovereign MAP West Branch Township, Ogemaw County330 Feet from North Line of Farm

" " East " " "

" " South " " "

330 " " West " " "

Feet from North Line of Section

" " East " " "

2310 " " South " " "330 " " West " " "LEGEND

O LOCATION

① RIG

⊕ DRILLING

⊗ GAS WELL

● OIL WELL

⬮ SMALL OIL WELL

⬮ DRY HOLE

⬮ DRY SHOWING OIL


⬮ DRY SHOWING GAS

⬮ ABANDONED LOCATION

⬮ ABANDONED GAS WELL

⬮ ABANDONED OIL WELL

NOTE: Below make tracing from map, (when no map is obtainable make sketch) showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location. Make copy to keep for reference and send original to Columbus office.



REMARKS:

Originally reported in SW Corner NW $\frac{1}{4}$ -NW $\frac{1}{4}$ 

SIGNED

Superintendent or Foreman.

STATE OF MICHIGAN  
DIVISION OF REVENUE  
DATE 8-17-33

CHARGE OF

LOCATION REPORT  
THE PURE OIL COMPANY


No. 42

DATE 8-17-33  
STATE Michigan COUNTY Ogemaw DIST. West Branch SEC. 29 TOWN 22N RANGE 2E  
WELL No. 1 (SERIAL No. 42) FARM Mary Griffin 40 ACRES  
NAME OF STREAM OR WATERS \_\_\_\_\_ QUADRANGLE SE-NW-SW  
OPERATOR W. J. Sovereign MAP West Branch Twp., Ogemaw Co.

Feet from North Line of Farm  
330 " " East " " "  
330 " " South " " "  
" " West " " "  
Feet from North Line of Section  
" " East " " "  
1650 " " South " " "  
990 " " West " " "

- LEGEND**
- |                  |                      |
|------------------|----------------------|
| ○ LOCATION       | ✦ DRY HOLE           |
| ① RIG            | ✦ DRY SHOWING OIL    |
| ⊕ DRILLING       | ✦ DRY SHOWING GAS    |
| ⊗ GAS WELL       | ⊗ ABANDONED LOCATION |
| ● OIL WELL       | ⊗ ABANDONED GAS WELL |
| ◆ SMALL OIL WELL | ⊗ ABANDONED OIL WELL |

NOTE: Below make tracing from map, (when no map is obtainable make sketch) showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location. Make copy to keep for reference and send original to Columbus office.



REMARKS:  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

SIGNED

*R. L. Yeager*  
Superintendent or Foreman.



